

Voluntary Recall Notification

19 November 2024

ATTY. CHERRYL G. CARBONELL

Officer-In-Charge Director
Consumer Protection and Advocacy Bureau

Subject: Product Recall of Pirelli Scorpion Trail II 150/70R18M/CTL 70V,
Metzeler Tourance Next 150/70R18M/CTL 70V,
Metzeler Tourance Next II 150/70R18M/CTL 70V

Dear Ma'am:

Greetings!

In the interest of public safety, Pirelli Asia Pte Ltd ("Pirelli") made a public announcement for a voluntary product recall of the Pirelli Scorpion Trail II 150/70R18M/CTL 70V, Metzeler Tourance Next 150/70R18M/CTL 70V, and Tourance Next II 150/70R18M/CTL 70V through its websites (<https://www.pirelli.com/tyres/en-ww/motorcycle/tyre-recall> and <https://www.metzeler.com/en-ww/tyre-recall>) and in-stores.

The relevant details are as follows:

Name of Product and Description	Tyre Brand: METZELER Tyre Pattern: TOURANCE NEXT Tyre Size: 150/70R18 M/C 70V Tyre Identification Number: (1)EB 0M X033 - from 4816 to 2424 Tyre Brand: METZELER Tyre Pattern: TOURANCE NEXT II Tyre Size: 150/70R18 M/C 70V Tyre Identification Number: (1)EB 0M 614L – from 3521 to 2624 Tyre Brand: Pirelli Tyre Pattern: SCORPION TRAIL II Tyre Size: 150/70R18 M/C 70V Tyre Identification Number: (1)EB 2M X032 – from 0117 to 4024
Reason for Recall	Under certain tyre service conditions (e.g., low inflation pressure, heavy load, road conditions, mileage at almost the half of tyre life, etc.), irregular tyre wear may develop, which, over time, may result in breakage of the zero degree reinforcement. If this condition is not promptly detected, it may lead to potential detachment of parts of the tread layer and/or sudden air loss.
Background of the Issue	11/09/24: Triumph Motorcycles UK informed Pirelli of a potential quality issue reported in the field and causing warranty reports in the European market.

	<p>12/09/24: Compliance with legal requirements and Pirelli's internal validation tests were verified on the subject products; no anomalies were found. Historical factory traceability data showed no deviations.</p> <p>01/10/24, Based on the field claims reported from the markets and the potential safety risk linked to the issue, Pirelli decided to initiate this recall campaign in affected markets.</p>
Action/Remedy	<p>Letters will be sent to each of the distributors and dealers who purchased tyres for the replacement market, directing them to check their inventory to inspect the tyre identification number to determine if they have any affected tyres. Pirelli will also notify all customers for whom we have registration information, along with consumers that our distributors can identify, directing them to visit a Pirelli dealer to have their tyres checked. All tyres with a tyre identification number reflecting production during the affected period will be exchanged at no cost to the customer (including labor for mounting and balancing). Pirelli will inform all the dealers and distributors about the modality how to manage the stock returns.</p>
Consumer Contact	<p>bikepark851@yahoo.com Contact: +63 9175200951</p>

Respectfully,



SOO KOK HONG
Technical Service Engineer Manager

Pirelli Asia Pte Ltd.
Robinson 77,
77 Robinson Road,
#23-01
Singapore 068896